



Software Release Notes – D4000 Firmware v1.2.16

2022-03-28

Table of Contents

Introduction	2
Fixed Defects	2
New Features	2
Known Issues and Limitations	2

Introduction

This document describes version 1.2.16 of the firmware for the thinkRF D4000 downconverter/tuner. It is distributed as a single binary file, *thinkRF_D4000_firmware_v1.2.16.img*.

This version of the D4000 firmware is compatible with all thinkRF D4000 products.

Fixed Defects

1. Reverted one of the changes to boot order from previous version which sometimes caused communication to slow down.

New Features

N/A

Known Issues and Limitations

1. The unit will sometimes boot to a fault state. In this case, the status LED will blink red and the unit should be rebooted.
2. At specific points within the operating band, the device is slower to tune. See [Support Articles](#) for details.

Document Revision History

This section summarizes document revision history.

Document Version	Release Date	Revisions and Notes
v1.0	2022-03-28	First release for firmware v1.2.16.

Contact us for more information

thinkRF Support website provides online documents for resolving technical issues with thinkRF products at <http://www.thinkrf.com/resources>.

For all customers who hold a valid end-user license, thinkRF provides technical assistance 9 AM to 5 PM Eastern Time, Monday to Friday. Contact us at <https://www.thinkrf.com/support> or by calling **+1.613.369.5104**.

© 2022 thinkRF Corporation, Ottawa, Canada, www.thinkrf.com

Trade names are trademarks of the owners.

These specifications are preliminary, non-warranted, and subject to change without notice.